

City of Detroit
Department of Recreation Performance Audit
Exhibit 4 – Chandler Golf Clubhouse

Overall Evaluation – Good

- Clubhouse was clean and pleasing to be in.
- Parking lot had well marked lines and was free of debris. However, paving was cracked.
- Area around the grounds had some debris.
- Bathrooms were clean with fixtures in good condition.



This parking lot was clean and had clearly marked parking places. However, the pavement, as a whole was full of cracks.

City of Detroit
Department of Recreation Performance Audit
Exhibit 4 – Chandler Golf Clubhouse



This sidewalk was clean; grass was cut and free of debris.



Light fixtures were clean and bright.

City of Detroit
Department of Recreation Performance Audit
Exhibit 4 – Chandler Golf Clubhouse



Portions of the men's bathroom were shiny clean.



The fixtures in the men's bathroom were very clean, walls were painted and in good condition.